

General Engine info	
Model and type of engine	LEAP-1B28
Current power rating of engine	LEAP-1B28
EGT Margin of engine deg C	
EGT Margin value date	
Current Location	WERC-US
Engine at date:	16-Jun-2023
Current TSN of engine:	0.00
Current CSN of engine:	0
Last installation /Shop input:	16-Jun-23
TSN of last installation / shop input:	0.00
CSN of last installation / shop input:	0

Non Limited Parts Information			
Name	Part Number	Serial Number	
Shipping Stand Cradle	TBD	TBD	
Shipping Stand Base	TBD	TBD	

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:	
QEC Kit p/n: QECMX737-93 less Hydraulic Pump, IDG, & parts identified in the WLFC QEC/Accessory Inventory.	
EGT Margin: 84 deg C (at LEAP-1B28 thrust rating - hot day performance)	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
LEAP-1B25	Multiple	7,600
LEAP-1B27	Multiple	7,600
LEAP-1B28	HPT Rotor [HPT Stg 2 Disk]	7,200

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	N/A	N/A	N/A
Date Limit	Engine Preservation	15 Jun 24	365

Last Shop Visit Information			
Time since last HSV	Hours	Cycles	
Time since last SV	0.00 Hours	0 Cycles	
Last Repair Agency	WERC-US		
Last SV Workscope	Preservation		
Airworthiness Release	16-Jun-23		FAA EASA

**LLP Parts**

Module Name	Name	Part Number	Serial No	Total Hours	Total Cycles	Cycles Used	Cycles Used	Cycles Used	Cycles Limit	Cycles Limit	Cycles Limit	Cycles Remaining	Cycles Remaining	Cycles Remaining
						LEAP-1B25	LEAP-1B27	LEAP-1B28	LEAP-1B25	LEAP-1B27	LEAP-1B28	LEAP-1B25	LEAP-1B27	LEAP-1B28
Fan Rotor	Fan Disk	364-040-010-0	HB153200	0	0	0	0	0	21,600	21,600	21,600	21,600	21,600	21,600
Fan Rotor	LPC Spool	364-905-100-0	MA661014	0	0	0	0	0	30,000	30,000	30,000	30,000	30,000	30,000
1 & 2 Brg Support Assy	LPC Shaft	364-045-020-0	HD106855	0	0	0	0	0	30,000	30,000	30,000	30,000	30,000	30,000
HPC Rotor	Compressor Rotor Stg 1 Blisk	2639M71G02	TMT1M94D	0	0	0	0	0	17,500	17,500	17,500	17,500	17,500	17,500
HPC Rotor	Compressor Rotor Stg 6-10 Spool	2552M06G04	GWN15H0R	0	0	0	0	0	7,600	7,600	7,300	7,600	7,600	7,300
HPC Rotor	Compressor Rotor Stg 2 Blisk	2552M02P02	TMT1M1HU	0	0	0	0	0	15,000	15,000	10,000	15,000	15,000	10,000
HPC Rotor	Compressor Rotor Stg 3-4 Blisk	2552M03G03	TMT1KP4K	0	0	0	0	0	15,000	15,000	10,000	15,000	15,000	10,000
HPC Rotor	Compressor Rotor Stg 5 Blisk	2552M05P02	GLHW31K9	0	0	0	0	0	15,000	15,000	10,000	15,000	15,000	10,000
HPC Rotor	Impeller Tube Support	2552M07P01	XAERC065	0	0	0	0	0	15,000	15,000	10,000	15,000	15,000	10,000
HPC Rotor	Rotating Seal	2552M09P01	NCU9556F	0	0	0	0	0	15,000	15,000	10,000	15,000	15,000	10,000
HPT Rotor	Forward Outer Seal	2596M44P02	TMT1LNLF	0	0	0	0	0	14,500	14,500	10,000	14,500	14,500	10,000
HPT Rotor	HPT Stg 1 Disk	2600M21G02	GWN15EH7	0	0	0	0	0	11,200	11,200	10,000	11,200	11,200	10,000
HPT Rotor	HPT Interstage Seal	2600M25P02	FIA1YWJT	0	0	0	0	0	8,400	8,400	8,000	8,400	8,400	8,000
HPT Rotor	HPT Stg 2 Disk	2547M01G02	TMT1LTE4	0	0	0	0	0	7,900	7,900	7,200	7,900	7,900	7,200
HPT Rotor	HPT Aft Rotating Seal	2547M40P02	TMT1LRD8	0	0	0	0	0	13,300	13,300	10,000	13,300	13,300	10,000
LPT Rotor	LPT Stg 1 Disk	364-021-030-0	PC940879	0	0	0	0	0	7,600	7,600	7,600	7,600	7,600	7,600
LPT Rotor	LPT Stg 2 Disk	364-021-130-0	HF975062	0	0	0	0	0	8,000	8,000	8,000	8,000	8,000	8,000
LPT Rotor	LPT Stg 3 Disk	364-021-230-0	HE655158	0	0	0	0	0	11,300	11,300	11,300	11,300	11,300	11,300
LPT Rotor	LPT Stg 4 Disk	364-001-611-0	PC886015	0	0	0	0	0	9,300	9,300	9,300	9,300	9,300	9,300
LPT Rotor	LPT Stg 5 Disk	364-600-011-0	GA014548	0	0	0	0	0	17,400	17,400	17,400	17,400	17,400	17,400
LPT Rotor	LPT Shaft	364-035-610-0	PF020976	0	0	0	0	0	7,900	7,900	7,900	7,900	7,900	7,900
Stationary Parts	HPT Case	2541M81G01	TMT1M7FG	0	0	0	0	0	15,000	15,000	15,000	15,000	15,000	15,000
Stationary Parts	Combustion Case Assy	2548M30G08	CDACUY05	0	0	0	0	0	13,000	13,000	13,000	13,000	13,000	13,000

Authorising Signature \_\_\_\_\_

Date \_\_\_\_\_

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.

General Engine info	
Model and type of engine	LEAP-1B28
Current power rating of engine	LEAP-1B28
EGT Margin of engine deg C	
EGT Margin value date	
Current Location	WERC-US
Engine at date:	16-Jun-2023
Current TSN of engine:	0.00
Current CSN of engine:	0
Last installation /Shop input:	16-Jun-23
TSN of last installation / shop input:	0.00
CSN of last installation / shop input:	0

Non Limited Parts Information			
Name	Part Number	Serial Number	
Shipping Stand Cradle	TBD	TBD	
Shipping Stand Base	TBD	TBD	

**Module status**

Name	IIN#	Part Number	Serial No	TSN FH	CSN
Fan Rotor	1	364-000-206-0	3F002737	0	0
1 & 2 Brg Support Assy	2	364-000-303-0	3G002685	0	0
HPC Rotor	4	2540M53G07	CMA60A755	0	0
Spool Assy 6-10	4	2552M06G04	GWN15HOR	0	0
HPT Rotor	5	2540M57G06	TRT60A755	0	0
LPT Rotor	6	364-000-802-0	3K002799	0	0
Stationary Parts	7	2611M10G06	ALK46697	0	0
HPT Blades	8	2747M52P02	VARIOUS	0	0

Aircraft Information	
Aircraft registration:	N/A
Position:	N/A
Current TSN of Aircraft:	N/A
Current CSN of Aircraft:	N/A
TSN of Aircraft at last installation:	N/A
CSN of Aircraft at last installation:	N/A
<b>Engine Status</b>	In Storage

Engine Comments:	
QEC Kit p/n: QECMX737-93 less Hydraulic Pump, IDG, & parts identified in the WLFC QEC/Accessory Inventory.	
EGT Margin: 84 deg C (at LEAP-1B28 thrust rating - hot day performance)	

Limiting Part Information		
Power Rating	Limiting Part	Cycles Remaining
LEAP-1B25	Multiple	7,600
LEAP-1B27	Multiple	7,600
LEAP-1B28	HPT Rotor [HPT Stg 2 Disk]	7,200

Limiting Inspection Information			
Type	Description	Limit	Remaining
Hour Limit	N/A	N/A	N/A
Cycle Limit	N/A	N/A	N/A
Date Limit	Engine Preservation	15 Jun 24	365

Last Shop Visit Information			
Time since last HSV	Hours	Cycles	
Time since last SV	0.00 Hours	0 Cycles	
Last Repair Agency	WERC-US		
Last SV Workslope	Preservation		
Airworthiness Release	16-Jun-23	FAA EASA	

Authorising Signature

Date

Although the information in this report has been obtained from sources which Willis Lease Finance Corporation (as Servicer) believes to be reliable, any such information may be incomplete or condensed. All data and information included in this report is for information purposes only, and is not intended as official documentation with respect to the purchase of this engine.